

Cymru Scaffold Inspections

Working at Height Regulations 2005

Scaffold Inspection Report

Inspection of places of Work at Height. The scaffolding structures Unique Numbered Tag conform to:	BS EN 12811/TG20:21
Scaffolding Inspection has been carried out at the site listed in accordance with:	Working at Height Regulation 12 & 13, 2005
Working at Height Regulation (2005)	Reports of results of every inspection made in pursuance of Regulation 12 & 13
The Provision and Use of Work Equipment Regulation 1998, Report of results of every inspection made in pursuance of Regulation 6(3)	Working at Height SG4:22 Preventing Falls in Scaffolding Operations
Location of Scaffold at Site:	Access Scaffold near Pipe Support, Trauma Unit, Prince Charles Hospital, Prince Charles Hospital, Merthyr Tydfil, CF47 9DT
Name & Address of the company/person on whose behalf the inspection was carried out:	Kevin Oliver, Site Manager, Tilbury Douglas Construction Ltd Tel: 01685 384174 Mobile: 07425 635973 Email: kevin.l.oliver@tilburydouglas.co.uk Web site: www.tilburydouglas.co.uk
Name & Address of the company/person at Site that is the Contact for all Scaffold Inspection issues of behalf on Tilbury Douglas	Various Site Engineers depending on Area of Scaffold at Tilbury Douglas, Prince Charles Hospital, Merthyr Tydfil, CF47 9DT (Name listed below for who is responsible for this Scaffold).
Location of the place of work inspected (Site Address):	Prince Charles Hospital, Merthyr Tydfil, CF47 9DT
Scaffold erected by (Scaffold Contractor):	Shield Environmental Services, Tremorfa Industrial Estate, 11 Martin Rd, Cardiff CF24 5SD
Erected date:	6th March 2023 (Modification since that date have taken place)
Description of Scaffold:	Access Scaffold near to Pipe Support Scaffold.
Dimensions of Scaffold:	Various Dimensions
Ground Conditions for Edge Protection Handrails:	Excellent, with no issues to report upon, the area below Scaffold has not been undermined or subject to recent Groundworks.
Handover Certificate Date of Issue and Handover Cert No:	HO 5062 & 4457 Date: 6-3-2023 & 5-6-2023 as SHE 138 prior to modifications.
Scaffold Design & Number of Designed Scaffold	N/a
Unique Scaffold Identity Number:	SHE 155
Date of Scaffold Inspection:	Tuesday 12th March 2024
Time of Scaffold Inspection:	14:30-16:30
Status of scaffold:	No Scaffold materials need to be removed from the Working Lifts, Access
Weather conditions at time of scaffold inspection:	Wet Conditions
Matters identified during scaffold inspection:	As per Photographic Logs
Can work be carried out safely? (Yes/No):	No
Principle Contractor reported to:	Aled Daniel, Tilbury Douglas, Prince Charles Hospital, Merthyr Tydfil, CF47 9DT
Scaffold Contractor reported to:	Barry Lewis, Shield Environmental Services, Tremorfa Industrial Estate, 11 Martin Rd, Cardiff CF24 5SD 029 20 448 040 or 07788318016
Remedial action to be taken:	As per Photographic Logs: Scaffold materials need to be removed from the Working Lifts. Access and Egress is limited in this area on the Working Lifts. Void needs to be eliminated on Working Lift. Brickguards required for Scaffold. Handover Certificate is required to be produced since the adaptations were made to the Scaffold. Scaffold can be accessed by using the newly installed Haki Staircase. Position of Ledger Bracing makes Access & Egress difficult in places. Single Fittings have been used to secure the Handrails as opposed to Doubler Couplers. Scaffold Contractor needs to be aware of Damaged Board when the Scaffold is being dismantled. Lapped Boards are a potential tripping hazard on the Working Lift. The Trap Door would not close due to the position of the Access ladder. Void needs to be eliminated in order to prevent objects falling from height, Access ladder needs to be set correctly.
Further action to be taken:	None
Name of Scaffold Inspector:	Donald Murray
Qualifications and Details of Scaffold Inspector:	CISRS Advanced Scaffold Inspector:
CISRS Registration Number:	Registration No: 40740524
Expiry Date:	Expires: November 28th 2028
Contact Details:	Tel: 07980985053 Email: donmurray969@outlook.com