

# Cymru Scaffold Inspections

## Working at Height Regulations 2005

### Scaffold Inspection Report

Inspection of places of Work at Height. The scaffolding structures Unique Numbered Tag conform to: EN 12811/TG20:21	BS
Scaffolding Inspection has been carried out at the site listed in accordance with: Working at Height Regulation 12 & 13, 2005	
Working at Height Regulation (2005) Reports of results of every inspection made in pursuance of Regulation 12 & 13	
The Provision and Use of Work Equipment Regulation 1998, Report of results of every inspection made in pursuance of Regulation 6(3)	
Working at Height SG4:22 Preventing Falls in Scaffolding Operations	
<b>Location of Scaffold at Site:</b>	<b>Plant Room C, Prince Charles Hospital, Prince Charles Hospital, Merthyr Tydfil, CF47 9DT</b>
<b>Name &amp; Address of the company/person on whose behalf the inspection was carried out:</b>	<b>Kevin Oliver, Site Manager, Tilbury Douglas Construction Ltd</b> Tel: 01685 384174 Mobile: 07425 635973 Email: kevin.l.oliver@tilburydouglas.co.uk Web site: www.tilburydouglas.co.uk
<b>Name &amp; Address of the company/person at Site that is the Contact for all Scaffold Inspection issues of behalf on Tilbury Douglas</b>	Various Site Engineers depending on Area of Scaffold at Tilbury Douglas, Prince Charles Hospital, Merthyr Tydfil, CF47 9DT (Name listed below for who is responsible for this Scaffold).
<b>Location of the place of work inspected (Site Address):</b>	Prince Charles Hospital, Merthyr Tydfil, CF47 9DT
<b>Scaffold erected by (Scaffold Contractor):</b>	Shield Environmental Services, Tremorfa Industrial Estate, 11 Martin Rd, Cardiff CF24 5SD
<b>Erected date:</b>	Mid May 2023
<b>Description of Scaffold:</b>	Access Scaffold, Loading Bays and Haki Staircases at Plant Room C
<b>Dimensions of Scaffold:</b>	Various Dimensions
<b>Ground Conditions for Edge Protection Handrails:</b>	Excellent, with no issues to report upon, the area below Scaffold has not been undermined or subject to recent Groundworks.
<b>Handover Certificate Date of Issue and Handover Cert No:</b>	HO 4455, 4456 & 4460 Date: 5-6-2023, 9-6-2023
<b>Scaffold Design &amp; Number of Designed Scaffold</b>	N/a
<b>Unique Scaffold Identity Number:</b>	SHE 136
<b>Date of Scaffold Inspection:</b>	Tuesday 12th March 2024
<b>Time of Scaffold Inspection:</b>	14:30-16:30
<b>Status of scaffold:</b>	Passed with observations (Some Sections have been modified/dismantled).
<b>Weather conditions at time of scaffold inspection:</b>	Wet Conditions
<b>Matters identified during scaffold inspection:</b>	As per Photographic Logs
<b>Can work be carried out safely? (Yes/No):</b>	Yes
<b>Principle Contractor reported to:</b>	Brendan O' Hara, Tilbury Douglas, Prince Charles Hospital, Merthyr Tydfil, CF47 9DT
<b>Scaffold Contractor reported to:</b>	Barry Lewis, Shield Environmental Services, Tremorfa Industrial Estate, 11 Martin Rd, Cardiff CF24 5SD 029 20 448 040 or 07788318016
<b>Remedial action to be taken:</b>	As per Photographic Logs: Scaffold materials need to be removed from the Working Lift, Voids need to be eliminated near where the Hoist is based, Trunking is potential tripping hazard, Scaffold materials need to be removed at the earliest opportunity. Some Working Lifts have no Toeboards due to Project Requirements. Scaffold being progressively dismantled in some areas.
<b>Further action to be taken:</b>	None
<b>Name of Scaffold Inspector:</b>	Donald Murray
<b>Qualifications and Details of Scaffold Inspector:</b>	CISRS Advanced Scaffold Inspector:
<b>CISRS Registration Number:</b>	Registration No: 40740524
<b>Expiry Date:</b>	Expires: November 28th 2028
<b>Contact Details:</b>	Tel: 07980985053 Email donmurray969@outlook.com