	• ر
Cymru Scaffold Inspections	
Working at Height Regulations 2005	
Scaffold Inspection Report	
Inspection of places of Work at Height. The scaffolding structures Unique Numbered Tag conform to: BS EN 12811/TG20:21	
Scaffolding Inspection has been carried out at the site listed in accordance with:	
Working at Height Regulation 12 & 13, 2005 Working at Height Regulation (2005)	
Reports of results of every inspection made in pursuance of Regulation 12 & 13	
The Provision and Use of Work Equipment Regulation 1998, Report of results of every inspection made in pursuance of	
Regulation 6(3) Working at Height SG4:22 Preventing Falls in Scaffolding Operations	
working at freight 304.22 Freventing Fails in Scarfolding Operations	
Location of Scaffold at Site:	Edge Protection Handrails and Access Scaffold on
	Roof of Pathology Building
	Prince Charles Hospital, Merthyr Tydfil, CF47 9DT
Name & Address of the company/person on whose	Kevin Oliver, Site Manager, Tilbury Douglas Construction Ltd Tel: 01685 384174 Mobile: 07425 635973
behalf the inspection was carried out:	Email: kevin.1.oliver@tilburydouglas.co.uk
	Web site: www.tilburydouglas.co.uk
Location of the place of work inspected (Site Address):	Prince Charles Hospital, Merthyr Tydfil, CF47 9DT
Scaffold erected by (Scaffold Contractor):	Shield Environmental Services, Tremorfa Industrial Estate, 11 Martin Rd. Cardiff CF24 5SD
Erected date:	Late October 2021
Description of Scaffold:	Edge Protection Handrials and Access Scaffold on Roof of Pathology Building
	U. S. D. S.
Dimensions of Scaffold:	Various Dimensions
Ground Conditions for Scaffold & Layher Staircase:	Excellent, with no issues to report upon, the area below Scaffold has not been underminded or subject to recent Groundworks.
Handover Certificate Date of Issue and Handover Cert No:	
Scaffold Design & Number of Designed Scaffold	N/a
Unique Scaffold Identity Number:	SHE 002
Date of Scaffold Inspection:	Tuesday 12th March 2024
Time of Scaffold Inspection:	14:30-16:30
Status of scaffold:	Passed with observations (No Access)
Weather conditions at time of scaffold inspection: Matters identified during scaffold inspection:	Wet Conditions As per Photographic Logs
Can work be carried out safely? (Yes/No):	No access at the time of the Scaffold Inspections
Principle Contractor reported to:	Paul Manuel, Tilbury Douglas, Prince Charles Hospital, Merthyr Tydfil, CF47 9DT
Scaffold Contractor reported to:	Barry Lewis, Shield Environmental Services,
	Tremorfa Industrial Estate,
	11 Martin Rd, Cardiff CF24 5SD 029 20 448 040 or 07788318016
Remedial action to be taken:	As per Photographic Logs:
	As per Photographic Logs, Access Door is locked and Access/Egress is not permitted at the time of the Scaffold Inspections.
Further action to be taken:	None
Name of Scaffold Inspector:	Donald Murray
Qualifications and Details of Scaffold Inspector:	CISRS Advanced Scaffold Inspector:
CISRS Registration Number:	Registration No: 40740524
Expiry Date:	Expires: November 28th 2028
Contact Details:	Tel: 07980985053 Email: donmurray969@outlook.com