

# Cymru Scaffold Inspections

## Working at Height Regulations 2005

### Scaffold Inspection Report

Inspection of places of Work at Height. The scaffolding structures Unique Numbered Tag conform to:	BS EN 12811/TG20:21
Scaffolding Inspection has been carried out at the site listed in accordance with:	Working at Height Regulation 12 & 13, 2005
Working at Height Regulation (2005)	Reports of results of every inspection made in pursuance of Regulation 12 & 13
The Provision and Use of Work Equipment Regulation 1998, Report of results of every inspection made in pursuance of Regulation 6(3)	
Working at Height SG4:22 Preventing Falls in Scaffolding Operations	
<b>Location of Scaffold at Site:</b>	<b>ECC Courtyard and Crane Access Layher Staircase, Prince Charles Hospital, Merthyr Tydfil, CF47 9DT</b>
<b>Name &amp; Address of the company/person on whose behalf the inspection was carried out:</b>	<b>Kevin Oliver, Site Manager, Tilbury Douglas Construction Ltd</b> Tel: 01685 384174 Mobile: 07425 635973 Email: kevin.l.oliver@tilburydouglas.co.uk Web site: www.tilburydouglas.co.uk
<b>Name &amp; Address of the company/person at Site that is the Contact for all Scaffold Inspection issues of behalf on Tilbury Douglas</b>	Various Site Engineers depending on Area of Scaffold at Tilbury Douglas, Prince Charles Hospital, Merthyr Tydfil, CF47 9DT <b>(Name listed below for who is responsible for this Scaffold).</b>
<b>Location of the place of work inspected (Site Address):</b>	Prince Charles Hospital, Merthyr Tydfil, CF47 9DT
<b>Scaffold erected by (Scaffold Contractor):</b>	Shield Environmental Services, Tremorfa Industrial Estate, 11 Martin Rd, Cardiff CF24 5SD
<b>Erected date:</b>	21st November 2021
<b>Description of Scaffold:</b>	Free Standing Layher Staircase and Lifting Gear Scaffold
<b>Dimensions of Scaffold:</b>	Various Dimensions
<b>Ground Conditions for Layher Staircase &amp; Access Scaffold:</b>	Excellent, with no issues to report upon, the area below Scaffold has not been undermined or subject to recent Groundworks.
<b>Handover Certificate Date of Issue and Handover Cert No:</b>	
<b>Scaffold Design &amp; Number of Designed Scaffold</b>	21/ORYX/10/675 & 21/ORYX/10/675 Oryx Designs, Little Woodlands, 61 Bath Road, Bristol, BS30 6ES Tel: 01173 290050 Email: harry@oryxdesingsltd.co.uk
<b>Unique Scaffold Identity Number:</b>	SHE 003
<b>Date of Scaffold Inspection:</b>	Tuesday 12th March 2024
<b>Time of Scaffold Inspection:</b>	14:30-16:30
<b>Status of scaffold:</b>	Passed
<b>Weather conditions at time of scaffold inspection:</b>	Wet Conditions
<b>Matters identified during scaffold inspection:</b>	As per Photographic Logs
<b>Can work be carried out safely? (Yes/No):</b>	Yes
<b>Principle Contractor reported to:</b>	<b>Chris Gwilliam, Tilbury Douglas, Prince Charles Hospital, Merthyr Tydfil, CF47 9DT</b>
<b>Scaffold Contractor reported to:</b>	Barry Lewis, Shield Environmental Services, Tremorfa Industrial Estate, Martin Rd, Cardiff CF24 5SD 029 20 448 040 or 07788318016 11
<b>Remedial action to be taken:</b>	As per Photo Logs: <b>No issues to report upon at time of the Scaffold Inspections.</b>
<b>Further action to be taken:</b>	None
<b>Name of Scaffold Inspector:</b>	Donald Murray
<b>Qualifications and Details of Scaffold Inspector:</b>	CISRS Advanced Scaffold Inspector:
<b>CISRS Registration Number:</b>	Registration No: 40740524
<b>Expiry Date:</b>	Expires: November 28th 2028
<b>Contact Details:</b>	Tel: 07980985053 Email: donmurray969@outlook.com