

Cymru Scaffold Inspections

Working at Height Regulations 2005

Scaffold Inspection Report

Inspection of places of Work at Height. The scaffolding structures Unique Numbered Tag conform to: EN 12811/TG20:21	BS
Scaffolding Inspection has been carried out at the site listed in accordance with: Working at Height Regulation 12 & 13, 2005	
Working at Height Regulation (2005) Reports of results of every inspection made in pursuance of Regulation 12 & 13	
The Provision and Use of Work Equipment Regulation 1998, Report of results of every inspection made in pursuance of Regulation 6(3)	
Working at Height SG4:22 Preventing Falls in Scaffolding Operations	
Location of Scaffold at Site:	The Green, Trefechan, Merthyr Tydfil, CF48 2EU
Name & Address of the company/person on whose behalf the inspection was carried out:	Gavin Spencer Delacey & Sons: Address: 1 Goat Mill Rd, Dowlais, Merthyr Tydfil CF48 3TD M
Name & Address of the company/person at Site that is the Contact for all Scaffold Inspection issues of behalf of Weatherproof Advisors	Gavin Spencer Delacey & Sons: Address: 1 Goat Mill Rd, Dowlais, Merthyr Tydfil CF48 3TD M
Location of the place of work inspected (Site Address):	The Green, Trefechan, Merthyr Tydfil, CF48 2EU
Scaffold erected by (Scaffold Contractor):	Appollo Scaffolding, 7 Regent St, Kingswood, Bristol, BS15 8JX
Erected date:	Not known at time of 1st Scaffold Inspections
Description of Scaffold:	Haki Staircase from Ground to Highest Working Lift of Scaffold
Dimensions of Scaffold:	Various dimensions
Ground Conditions for Haki Staircase:	Excellent, with no issues to report upon, the area below Scaffold has not been undermined or subject to recent Groundworks.
Handover Certificate Date of Issue and Handover Cert No:	Date of Issue:
Scaffold Design & Number of Designed Scaffold	N/a
Unique Scaffold Identity Number:	TER 002
Date of Scaffold Inspection:	Tuesday 12th March 2024
Time of Scaffold Inspection:	09:15-10:35
Status of scaffold:	Passed with observations
Weather conditions at time of scaffold inspection:	Wet conditions
Matters identified during scaffold inspection:	As per Photographic Logs
Can work be carried out safely? (Yes/No):	Yes
Principle Contractor reported to:	Gavin Spencer Delacey & Sons: Address: 1 Goat Mill Rd, Dowlais, Merthyr Tydfil CF48 3TD M
Scaffold Contractor reported to:	Appollo Scaffolding, 7 Regent St, Kingswood, Bristol, BS15 8JX Contact Details: 07712 659635
Remedial action to be taken:	As per Photo Logs: Handover Certificate is required for Haki Staircase, Haki Staircase is not included in the Design .
Further action to be taken:	None
Name of Scaffold Inspector:	Donald Murray
Qualifications and Details of Scaffold Inspector:	CISRS Advanced Scaffold Inspector:
CISRS Registration Number:	Registration No: 40740524
Expiry Date:	Expires: November 28th 2028
Contact Details:	Tel: 07980985053 Email: donmurray969@outlook.com