

Cymru Scaffold Inspections

Working at Height Regulations 2005

Scaffold Inspection Report

Inspection of places of Work at Height. The scaffolding structures Unique Numbered Tag conform to: EN 12811/TG20:21	BS
Scaffolding Inspection has been carried out at the site listed in accordance with: Working at Height Regulation 12 & 13, 2005	
Working at Height Regulation (2005)	
Reports of results of every inspection made in pursuance of Regulation 12 & 13	
The Provision and Use of Work Equipment Regulation 1998, Report of results of every inspection made in pursuance of Regulation 6(3)	
Working at Height SG4:22 Preventing Falls in Scaffolding Operations	
Location of Scaffold at Site:	Access Scaffold, Plant Room C Prince Charles Hospital, Merthyr Tydfil, CF47 9DT
Name & Address of the company/person on whose behalf the inspection was carried out:	Bradley Jones, Tilbury Douglas, Prince Charles Hospital, Merthyr Tydfil, CF47 9DT
Name & Address of the company/person on whose behalf the inspection was carried out:	Kevin Oliver, Site Manager, Tilbury Douglas Construction Ltd Tel: 01685 384174 Mobile: 07425 635973 Email: kevin.l.oliver@tilburydouglas.co.uk Web site: www.tilburydouglas.co.uk
Location of the place of work inspected (Site Address):	Prince Charles Hospital, Merthyr Tydfil, CF47 9DT
Scaffold erected by (Scaffold Contractor):	Shield Environmental Services, Tremorfa Industrial Estate, 11 Martin Rd, Cardiff CF24 5SD
Erected date:	Not known
Description of Scaffold:	Access Scaffold, Plant Room C
Dimensions of Scaffold:	1.2m x 1.2m Working Lift
Ground Conditions for Scaffold:	Excellent, with no issues to report upon, the area below Scaffold has not been undermined or subject to recent Groundworks.
Handover Certificate Date of Issue and Handover Cert No:	Handover Certificate: 6051 Date: 9-01-2024
Scaffold Design & Number of Designed Scaffold	N/a
Unique Scaffold Identity Number:	SHE 170
Date of Scaffold Inspection:	Tuesday 12th March 2024
Time of Scaffold Inspection:	14:30-16:30
Status of scaffold:	Passed
Weather conditions at time of scaffold inspection:	Wet Conditions
Matters identified during scaffold inspection:	As per Photographic Logs
Can work be carried out safely? (Yes/No):	Yes
Principle Contractor reported to:	Brendan O Hara , Tilbury Douglas, Prince Charles Hospital, Merthyr Tydfil, CF47 9DT
Scaffold Contractor reported to:	Barry Lewis, Shield Environmental Services, Tremorfa Industrial Estate, 11 Martin Rd, Cardiff CF24 5SD 029 20 448 040 or 07788318016
Remedial action to be taken:	As per Photo Logs: No issues to report upon.
Further action to be taken:	None
Name of Scaffold Inspector:	Donald Murray
Qualifications and Details of Scaffold Inspector:	CISRS Advanced Scaffold Inspector:
CISRS Registration Number:	Registration No: 40740524
Expiry Date:	Expires: November 28th 2028
Contact Details:	Tel: 07980985053 Email: donmurray969@outlook.com