

Cymru Scaffold Inspections

Working at Height Regulations 2005

Scaffold Inspection Report

Inspection of places of Work at Height. The scaffolding structures Unique Numbered Tag conform to: EN 12811/TG20:21	BS
Scaffolding Inspection has been carried out at the site listed in accordance with: Working at Height Regulation 12 & 13, 2005	
Working at Height Regulation (2005) Reports of results of every inspection made in pursuance of Regulation 12 & 13	
The Provision and Use of Work Equipment Regulation 1998, Report of results of every inspection made in pursuance of Regulation 6(3)	
Working at Height SG4:22 Preventing Falls in Scaffolding Operations	
Location of Scaffold at Site:	Sheeted Enclosure, Hospital Entrance, Prince Charles Hospital, Merthyr Tydfil, CF47 9DT
Name & Address of the company/person on whose behalf the inspection was carried out:	Kevin Oliver, Site Manager, Tilbury Douglas Construction Ltd Tel: 01685 384174 Mobile: 07425 635973 Email: kevin.l.oliver@tilburydouglas.co.uk Web site: www.tilburydouglas.co.uk
Name & Address of the company/person at Site that is the Contact for all Scaffold Inspection issues of behalf on Tilbury Douglas	Various Site Engineers depending on Area of Scaffold at Tilbury Douglas, Prince Charles Hospital, Merthyr Tydfil, CF47 9DT (Name listed below for who is responsible for this Scaffold).
Location of the place of work inspected (Site Address):	Main Entrance to Hospital, Prince Charles Hospital, Merthyr Tydfil, CF47 9DT
Scaffold erected by (Scaffold Contractor):	Shield Environmental Services, Tremorfa Industrial Estate, 11 Martin Rd, Cardiff CF24 5SD
Erected date:	Late January 2022
Description of Scaffold:	Sheeted Enclosure at Hospital Entrance
Dimensions of Scaffold:	Various Dimensions
Ground Conditions for Sheeted Scaffold on Roof:	Excellent, with no issues to report upon, the area below Scaffold has not been undermined or subject to recent Groundworks.
Handover Certificate Date of Issue and Handover Cert No:	Handover Cert Number:
Scaffold Design & Number of Designed Scaffold	N/a
Unique Scaffold Identity Number:	SHE 005
Date of Scaffold Inspection:	Tuesday 12th March 2024
Time of Scaffold Inspection:	14:30-16:30
Status of scaffold:	Passed
Weather conditions at time of scaffold inspection:	Wet Conditions
Matters identified during scaffold inspection:	As per Photographic Logs
Can work be carried out safely? (Yes/No):	Yes
Principle Contractor reported to:	Lee Thomas , Tilbury Douglas, Prince Charles Hospital, Merthyr Tydfil, CF47 9DT
Scaffold Contractor reported to:	Barry Lewis, Shield Environmental Services, Tremorfa Industrial Estate, 11 Martin Rd, Cardiff CF24 5SD 029 20 448 040 or 07788318016
Remedial action to be taken:	As per Photo Logs: No issues to report upon at time of the Scaffold Inspections, one of the Boards needs to be replaced in its original position.
Further action to be taken:	None
Name of Scaffold Inspector:	Donald Murray
Qualifications and Details of Scaffold Inspector:	CISRS Advanced Scaffold Inspector:
CISRS Registration Number:	Registration No: 40740524
Expiry Date:	Expires: November 28th 2028
Contact Details:	Tel: 07980985053 Email: donmurray969@outlook.com